THE COMPENSATED TWO-CIRCUIT ELECTRODYNAMOMETER.

By Edward B. Rosa.

1. ALTERNATING CURRENT AMMETERS FOR PRECISION MEASUREMENTS.

The Kelvin balance is a standard instrument for the measurement of alternating currents, but is a slow instrument in practice and is difficult to use for currents not entirely steady. Moreover, in the instruments for heavy currents there are eddy currents in the metal parts of the balance. This causes an appreciable error, at least with currents of higher than the ordinary frequency, and with currents of distorted wave shape.

The new Leeds and Northrup comparator is an excellent instrument for precision measurements of large or small alternating currents, and we have found it very useful at the Bureau of Standards. It is a differential hot wire instrument and is used in connection with a shunt for large currents. It is essential in this instrument also, for precision measurements, that the current to be measured shall remain very steady; and at least for currents of frequency higher than the ordinary, the self-inductances of the shunts used with the instrument should be known.

The use of an electrometer in connection with a standardized shunt for measuring large alternating currents is subject to the same condition, that the inductance of the shunt must be known; and for shunts of very small resistances on relatively high frequencies, or for distorted wave shapes, the inductance must be very small indeed to be neglected. Thus, with a shunt of .001 ohm (for measuring say 200 to 500 amperes) and a frequency of 180 cycles an inductance of only 100 cm, or 0.1 microhenry, would make the impedance of the shunt greater than its resistance by nearly one per cent, and hence introduce an error of this magnitude in the result, unless the

Fig. 1

Fig. 1.—Drawing of Heavy Current Ammeter.

Two-circuit electro-dynamometer, with current shunts, to measure alternating currents from 100 to 1,000 amperes. The field coil consists of two turns of heavy stranded cable B, B'; the two moving coils *c*, *c'* give an astatic system unaffected by distant stray fields, or by the earth's field when the instrument is calibrated by direct currents. The deflections are read on a curved scale by means of a telescope. A lever on the bottom of the lower suspension gives a ready means of changing the zero position of the moving system, required in testing the compensation for the self-inductance of the potential circuit, and in testing for the presence of eddy currents.

inductance were known and a correction applied. If, however, one is measuring currents not of sine wave form the correction can not be calculated unless the wave form is known. It is obviously better, if possible, in precision measurements, to employ an instrument that is free from error arising from the small residual inductance which can not be entirely eliminated even from a "non-inductive" shunt, and that is correct for all frequencies and all wave shapes.

2. THE TWO-CIRCUIT ELECTRODYNAMOMETER.

A fourth form of instrument which we have been using for some time at the Bureau of Standards, and which seems to meet these conditions, is a two-circuit electro-dynamometer, with standardized shunt. Several of these

instruments, for measuring alternating currents of different ranges, were built in the instrument shop of the Bureau about two years ago and have recently been carefully investigated. They are quick in action and convenient to operate, and

Fig. 2

when compensated for the resultant inductance and capacity of the moving coil circuit, they have the same constant for alternating current as for direct. They may, therefore, be calibrated by direct currents, measured by means of standard shunts, a potentiometer and standard cell, the moving coil circuit of the electro-dynamometer being connected to the terminals of a shunt designed to carry alternating current, the larger shunts being submerged in an oil bath which is water cooled and stirred. It is, of course, desirable that the inductance of the shunt be kept small, but no error arises from this cause, either in the ideal simple instrument or in the actual compensated instrument, the theory of which will be given presently.

That the reading of the ideal simple instrument is independent of the self-inductance of the shunt may easily be shown. By ideal simple instrument is meant one in which the self-inductance of the

moving coil circuit and the mutual inductance of the two circuits are both zero, while eddy currents in the region of the moving coils and capacity in the resistance R_2 are supposed absent. Fig. 2 shows the circuits of the instrument. The main current I to be measured flows in series through the shunt S and the fixed coil A of the electro-dynamometer. From the potential points a, b , of the shunt the potential current i flows through the resistance R_2 and the moving coils $B_1 B_2$ of the instrument. This current is proportional to the difference of potential between the points a, b , and therefore to the product of the current into the impedance of the shunt. Thus,

$$i = \frac{(I-i)\sqrt{r_1^2 + p^2 L_1^2}}{R_2} \quad (1)$$

where r_1 is the resistance and L_1 the inductance of the shunt, p being $2\pi n$. This current i lags behind the main current I by the angle ϕ , where

$$\cos \phi = \frac{r_1}{\sqrt{r_1^2 + p^2 L_1^2}}$$

Hence the torque of the instrument, which is proportional to I, i and $\cos \phi$ is

$$\begin{aligned} T &= K I i \cos \phi \\ &= \frac{K I (I-i) r_1}{R_2} \end{aligned} \quad (2)$$

That is, the deflection is unaffected by the self-inductance of the shunt. The constant K is determined by passing a direct current through the instrument, the potential current in that case being,

$$i = \frac{(I-i)r_1}{R_2}$$

The deflection is the same when the direct current is equal to the square root of the mean square of the alternating current. The deflection being independent of the frequency is also independent of the wave form.

3. THE COMPENSATED INSTRUMENT.

In the above simple theory of the two circuit electro-dynamometer it was assumed that L_2 and M , the self-inductance of the potential circuit and the mutual inductance between the two circuits, were zero. As this is not realized in the actual instrument it is necessary to calculate the effect upon the deflection of these quantities, as well as the effect of eddy currents in the fixed winding or other parts of the instrument.

In the potential circuit there are two electromotive forces acting, e_1 due to the current $I - i_1$ in the shunt (where I is the total current flowing, which passes through the fixed coil, and i_1 is the component of the current in the potential circuit in phase with I), and e_2 due to the mutual inductance M between the two coils. The first is equal to the current times the impedance, the second is proportional to M , I and the frequency. Thus, using complex quantities,

Fig. 3

$$\left. \begin{aligned} e_1 &= (I - i_1)(r + j\dot{p}L_1) \\ e_2 &= -j\dot{p}MI \\ e &= e_1 + e_2 \end{aligned} \right\} \quad (3)$$

The current I_2 in the potential circuit is equal to the electromotive force e divided by the impedance of the potential circuit, namely, $R_2 + j\dot{p}L_2$. Thus,

$$\begin{aligned} I_2 &= \frac{(I - i_1)(r + j\dot{p}L_1) - j\dot{p}MI}{R_2 + j\dot{p}L_2} \\ &= \frac{(I - i_1)(R_2r + \dot{p}^2L_1L_2) - \dot{p}^2ML_2I - j\dot{p}[(I - i_1)(rL_2 - R_2L_1) + MR_2I]}{R_2^2 + \dot{p}^2L_2^2} \end{aligned} \quad (4)$$

This current I_2 is not in phase with the main current, but lags by an angle ϕ such that

$$\tan \phi = \frac{p[(I-i_1)(L_2r - R_2L_1) + MR_2I]}{(I-i_1)(R_2r + p^2L_1L_2) - p^2ML_2I} \quad (5)$$

Putting i_1 and i_2 for the two components in phase and 90° out of phase with I , so that

$$I_2 = i_1 + ji_2$$

we have for the component in phase with the main current I ,

$$i_1 = \frac{(I-i_1)(R_2r + p^2L_1L_2) - p^2ML_2I}{R_2^2 + p^2L_2^2} \quad (6)$$

The component i_2 , 90° out of phase with I , contributes nothing to the torque on the moving coils and may be neglected. The torque due to the component i_1 is

$$\begin{aligned} T &= KIi_1 \\ &= \frac{KI(I-i_1)r}{R_2} \left[\frac{1 + \frac{p^2L_1L_2}{R_2r} - \frac{p^2ML_2}{R_2r} \frac{I}{I-i_1}}{1 + \frac{p^2L_2^2}{R_2^2}} \right] \end{aligned} \quad (7)$$

If L_2 , the self-inductance of the moving coil were zero, this expression for the torque would reduce to equation (2), which is the value for direct current. If L_2 is not zero, the expression in the bracket gives the correction to the torque, which depends not only on the constants L_1 and L_2 , but also on the variable mutual inductance M and the frequency of the current. If R_2 is large and the frequency is low, the correction can be neglected. But for frequencies as large as 100 to 180, and such resistances as we can use without reducing the deflection too much the correction may be important. I have therefore arranged to compensate the self-inductance of the potential circuit by a capacity, so as to make the potential current have the same phase as the impressed electromotive force in the potential circuit. This is equivalent to making $L_2 = 0$, and so making the correction in brackets in (7) equal to zero.

Fig. 4 represents the potential circuit of the dynamometer with

an outside resistance r_2 in parallel with which is a condenser C . Its terminals have been removed from the shunt and joined together, or what amounts to the same thing the two terminals are joined to the same point on the shunt, so that no electromotive force is impressed upon the potential circuit except that due to mutual inductance.

Fig. 4

The conductance from A to B is $\frac{1}{r_2} + jpC$

The impedance Z_2 is therefore

$$Z_2 = \frac{1}{\frac{1}{r_2} + jpC} = \frac{r_2}{1 + jpCr_2} = \frac{r_2 - jpCr_2^2}{1 + p^2C^2r_2^2}$$

The impedance of the remainder of the circuit, Z_1 , is

$$Z_1 = r_1 + jpL_2$$

The total impedance of the potential circuit is therefore

$$Z = r_1 + jpL_2 + \frac{r_2 - jpCr_2^2}{1 + p^2C^2r_2^2}$$

If $p^2C^2r_2^2$ can be neglected in comparison with unity, this reduces to

$$Z = r_1 + r_2 - jp(Cr_2^2 - L_2) \quad (8)$$

and if r_2 is so adjusted that $Cr_2^2 = L_2$, the impedance reduces to the

$$Z = r_1 + r_2 = R_2$$

That is, the impedance is equal to the ohmic resistance.

The compensation for the inductance in this case is true at all frequencies, and hence the correction factor in brackets in equation 7 reduces to unity.

In a particular case L_2 was 0.328 milli-henry, C was 1 microfarad, and hence r_2 was 18.1 ohms; $p^2 C^2 r_2^2$ was, therefore, for 180 cycles about .0004, and for 900 cycles, .01. The compensation is thus seen to be independent of frequency for a considerable range, and hence independent of the wave form.

4. APPLYING THE COMPENSATION.

To test the need of compensation join up the dynamometer as in Fig. 4 without the condenser or the auxiliary resistance r_2 and pass the full load current of the instrument through the fixed coil. If R_2 is the resistance of the moving coil circuit and L_2 its inductance, the current I_2 in the moving coil circuit will be,

$$I_2 = \frac{-jpMI}{R_2 + jpL_2} = \frac{-(R_2 - jpL_2)jpMI}{R_2^2 + p^2L_2^2} = \frac{-p^2L_2MI - jpMR_2I}{R_2^2 + p^2L_2^2} \quad (9)$$

$$= i_1 + ji_2$$

The component ji_2 produces no torque; the component i_1 gives a torque

$$T = KIi_1$$

$$= -\frac{Kp^2L_2MI^2}{R_2^2 + p^2L_2^2} \quad (10)$$

$$= -\frac{Kp^2L_2MI^2}{R_2^2}$$

when L_2 is small, as is usually the case, and $p^2L_2^2$ is negligible in comparison with R_2^2 .

If the moving coils are so placed that the mutual inductance M changes sign as the coils are deflected over the range of the scale, this torque will reverse sign accordingly. In an instrument with a torsion head where the moving coil always occupies the same

position, the position can be so chosen that M , and hence the torque due to mutual inductance, shall be zero. In a deflection instrument this is not practicable, but, as we have seen above, the torque is made zero by compensating with capacity so as to have the same effect as reducing L_2 to zero.

Fig. 5

By introducing a condenser and resistance r_2 into the circuit, varying the latter as necessary, the deflection can be reduced to zero for all positions of the moving coils, *provided there are no eddy currents in the fixed coil*. If there are eddy currents, which produce a torque in addition to that expressed by (10), the resistance r_2 in parallel with the capacity C required to give zero deflection will vary over the

Fig. 6

scale as shown in Fig. 5. AB represents a scale 1 meter long. The curve AC_1 shows how the compensating resistance r_2 varies over the first half of the scale, and C_2B represents it over the second part. The reading C corresponds to the position of the coil when the mutual inductance M is zero. Fig. 6 shows the curve when the eddy cur-

rent effect is very small, and the compensating resistance is constant except for a short distance in the region of zero mutual inductance, which may of course be displaced considerably from the center.

5. TORQUE DUE TO EDDY CURRENTS.

To investigate the effect of eddy currents in the fixed coil or in any masses of metal near the moving coils, assume a third circuit C (Fig. 7) inductively connected with the fixed coil A and the moving coil circuit B.

Fig. 7

Let M_1 be the mutual inductance of the fixed and moving coil circuits.

Let M_2 be the mutual inductance of the fixed and eddy current circuits.

Let M_3 be the mutual inductance of the moving coil and eddy current circuits.

Let the moving coil circuit be compensated for self-inductance so that we take L_2 as zero; L_3 is the self-inductance of the eddy current circuit. R_2 and R_3 are the resistances of the moving coil and eddy current circuits respectively.

Let I be the current in the fixed coil, its phase being taken as zero.

$I_2 = i'_2 + ji''_2$ is the current in the moving coil circuit.

$I_3 = i'_3 + ji''_3$ is the current in the eddy current circuit.

The electromotive force E_3 in the eddy current circuit is then

$$E_3 = -jpM_2I \quad (11)$$

neglecting the insignificant effect of the small current I_2 .

Dividing E_3 by the impedance of the eddy current circuit,

$$I_3 = \frac{-j\dot{p}M_2I}{R_3 + j\dot{p}L_3} = -\frac{\dot{p}^2M_2L_3I + j\dot{p}M_2R_3I}{R_3^2 + \dot{p}^2L_3^2} \quad (12)$$

$$\left. \begin{aligned} \therefore i'_3 &= -\frac{\dot{p}^2M_2L_3I}{R_3^2 + \dot{p}^2L_3^2} \quad (2) \\ i''_3 &= -\frac{\dot{p}M_2R_3I}{R_3^2 + \dot{p}^2L_3^2} \quad (4) \end{aligned} \right\} \quad (13)$$

The electromotive force E_2 acting in the moving coil circuit is due to the mutual inductance of the other two circuits. Thus:

$$\begin{aligned} E_2 &= -j\dot{p}M_1I - j\dot{p}M_3I_3 = -j\dot{p}M_1I - \frac{\dot{p}^2M_2M_3R_3I - j\dot{p}^3M_2M_3L_3I}{R_3^2 + \dot{p}^2L_3^2} \\ I_2 &= \frac{E_2}{R_2} = -\frac{\dot{p}^2M_2M_3R_3I}{R_2(R_3^2 + \dot{p}^2L_3^2)} - \frac{j\dot{p}I}{R_2} \left\{ M_1 - \frac{\dot{p}^2M_2M_3L_3}{R_3^2 + \dot{p}^2L_3^2} \right\} \\ &= i'_2 + ji''_2 \end{aligned} \quad (14)$$

$$\left. \begin{aligned} \therefore i'_2 &= -\frac{\dot{p}^2M_2M_3R_3I}{R_2(R_3^2 + \dot{p}^2L_3^2)} \quad (3) \\ i''_2 &= -\frac{\dot{p}I}{R_2} \left\{ M_1 - \frac{\dot{p}^2M_2M_3L_3}{R_3^2 + \dot{p}^2L_3^2} \right\} \quad (5) \end{aligned} \right\} \quad (15)$$

The resultant torque on the moving coil system is due to the current I_2 in the fields due to I and I_3 . The

Fig. 8.

rectangular components of these currents, which in general have different phases, are shown graphically in Fig. 8. The current i'_2 produces a torque with respect to I and i'_3 , while i''_2 produces a torque with respect to i''_3 . The whole torque T may be regarded as made up of two parts, T_1 and T_2 , where T_1 is due to the currents represented by the horizontal arrows and T_2

is due to the currents represented by the vertical arrows. If K_1 is the constant of the instrument for the field winding through which the current I flows, and K_3 the constant for the eddy current circuits, we shall have

$$T_1 = K_1 I i'_2 + K_3 i'_2 i'_3 = \frac{p^2 M_2 R_3 I^2}{R_2 (R_3^2 + p^2 L_3^2)} \left\{ -K_1 M_3 + \frac{K_3 p^2 M_2 M_3 L_3}{R_3^2 + p^2 L_3^2} \right\}$$

$$T_2 = K_3 i''_3 i''_2 = \frac{p^2 M_2 R_3 I^2}{R_2 (R_3^2 + p^2 L_3^2)} \left\{ +K_3 M_1 - \frac{K_3 p^2 M_2 M_3 L_3}{R_3^2 + p^2 L_3^2} \right\}$$

The total torque is therefore

$$T = T_1 + T_2 = -\frac{p^2 M_2 R_3 I^2}{R_2 (R_3^2 + p^2 L_3^2)} \left\{ K_3 M_1 - K_1 M_3 \right\} \quad (16)$$

In order to make this torque zero the quantity $K_3 M_1 - K_1 M_3$ must be made equal to zero, as none of the other quantities can be made zero except perhaps M_2 , and that only by rebuilding the instrument. The mutual inductances M_1 and M_3 each consist of two parts and we may write:

$$M_1 = M'_1 + M''_1 \quad \text{where } M'_1 = \text{constant} \\ M''_1 \propto K_1 = aK_1$$

$$M_3 = M'_3 + M''_3 \quad \text{where } M'_3 = \text{constant} \\ M''_3 \propto K_3 = aK_3$$

The constant parts of these mutual inductances, M'_1 and M'_3 , are due to the inductances of the fixed and eddy current circuits upon all the moving coil circuit exclusive of the moving coils themselves. The variable parts are the inductances upon the moving coils, which vary as the coils are deflected, and reverse sign as they pass through the position of no mutual inductance. The mutual inductance M''_1 is proportional to the strength of magnetic field at the coil due to unit current in the fixed coil, as is also the constant K_1 ; hence M''_1 is proportional to K_1 . Thus we have

$$K_3 M_1 - K_1 M_3 = K_3 M'_1 + aK_1 K_3 - K_1 M'_3 - aK_3 K_1 \\ = K_3 M'_1 - K_1 M'_3 = A, \text{ a constant.} \quad (17)$$

Thus if we adjust M'_1 so that $K_3 M'_1 = K_1 M'_3$ the constant A will be zero and the torque due to the eddy currents will be zero. This we can do by inserting a coil of a few turns in series with the moving coil circuit, *W* Fig. 7, and placing it in such a position with respect to the fixed coil that the mutual inductance M'_1 is given the desired value. This adjustment holds for all

positions of the moving coils and for all values and frequencies of the current.

Writing A for the bracket in equation (16) we have for the torque due to eddy currents and mutual inductance without the compensating inductance,

$$T = -\frac{p^2 M_2 R_3 I^2 A}{R_2 (R_3^2 + p^2 L_3^2)} \quad (18)$$

This equation I have verified experimentally¹ by placing coils of known resistance and inductance near the instrument and varying the several quantities separately. When L_3 and p are small the torque is proportional to p^2 , that is, to the *square of the frequency*; when pL_3 is large relatively to R_3 the torque is *independent of the frequency*. For the case of masses of metal the torque falls between these extremes and is approximately proportional to the frequency.

The torque is constant and in the same direction over the entire scale; hence it is easy to distinguish between the torque due to eddy currents and that due to L_2 the self-inductance of the moving coil circuit. The latter is variable and changes sign where M_1 is zero. Hence in making the double compensation one should change r_2 until the deflection is constant over the scale, then adjust the compensating inductance until it is reduced to zero. This compensation should be made with a heavy current in the field and as high a frequency as possible, and R_2 relatively small. At lower frequency the torque is smaller, and will be negligible if compensated as nearly as possible at the higher frequency.

6. VARYING THE RANGE OF THE INSTRUMENT.

To vary the constant of the instrument, the resistance R_2 may be increased by varying amounts above its minimum. The resistance of the moving coils and connections being r_1 and the compensating resistance being r_2 , the minimum value of R_2 is $r_1 + r_2$. Additional resistance r_3 may be added to any extent without disturbing the compensation, provided this resistance is free from inductance or

¹ In this verification as well as in the other experimental work with these instruments I have received valuable assistance from Messrs. M. G. Lloyd, P. G. Agnew, T. T. Fitch, and F. W. Grover.

capacity. This will vary K over a wide range and so enable one to measure a considerable range of current.

If r_3 does possess appreciable inductance or capacity it will slightly alter the compensation, but usually not appreciably. For the inductance or capacity of r_3 is not likely to be appreciable in comparison with L_2 unless r_3 is large; and if r_3 and hence R_2 is large, the torque due to L_2 for which compensation is made will be very small, being inversely proportional to R_2 . However, as a test for compensation can quickly be made at any time, there is no necessity for the compensation of the instrument to be wrong, even though the potential resistance R_2 is frequently altered.

One of the chief advantages of this form of alternating current ammeter is the ease with which the constant can be altered in a known ratio. The formula for the torque given by equation (2), which is (7) with the correction factor reduced to unity, may be written,

$$D = K_1 \frac{I^2 r_1}{R_2}$$

for heavy currents, where i is inappreciable in comparison with I and D is the deflection. K_1 will not of course be quite constant over the scale. If R_2 is increased in the ratio of 4, 9, 16, etc., the value of I for the same deflection will be increased 2, 3, 4, etc., times. If r_1 is decreased 4 times (by using a shunt of larger capacity and lower resistance), a given deflection will correspond to a current twice as large. Thus the heaviest current the instrument can carry (suppose 100 amperes) will be measured with the smallest value of r_1 and the largest value of R_2 , and this will give a full scale deflection. For the lightest currents to be measured, suppose r is 10 times larger and R_2 10 times smaller, then 10 amperes will give full scale deflection, and 5 amperes can be measured with good accuracy. If the instrument has a double winding, a still wider range of current can be measured with satisfactory accuracy.

For the heavy current ammeter shown in Fig. 1 there are two manganin shunts provided, arranged as shown in Fig. 9. Either one can be shortcircuited by the copper block a , b being an insulating block; a and b can be interchanged in position quickly when the screw S is released.

The heavy bar conductors are not disturbed in this change. The shunts are submerged in oil, which is cooled by a circulation of water. Thus the temperature of the shunts will be raised very little by the full load currents for which they are designed, namely, 250 and 1,000 amperes.

7. WATTMETERS.

Two-circuit electrodynometers are very commonly used as wattmeters, with a high resistance in the potential circuit. For measuring the power in circuits of relatively high electromotive force and of large power factor, the effect of the usually small inductance of the coils of the potential circuit and of any slight eddy currents that may be present is negligible. But when the wattmeter is used on circuits of very low electromotive force, where the resistance R_2 must be made small, or when the power factor is very small, these sources of error may be very important. It is therefore desirable to use the same compensation of resistance in parallel with capacity in precision wattmeters as is used in two-circuit ammeters, and also to test for the presence of eddy currents. If these eddy currents are in the metallic parts of the instrument (the field conductors being so thoroughly stranded and insulated as to obviate them in the field windings), they may be fully compensated

Fig. 9

for by a loop in the potential circuit, placed inductively with respect to the field, as described above. If, however, they are in the field coil themselves, this compensation for their torque still leaves a possible source of error—namely, in the different distribution of the alternating current in the field coils from that of the direct current employed in calibrating the instrument. The field coils should therefore be carefully protected from eddy currents by making them of insulated strands.

A wattmeter compensated in this manner may be employed to measure the power expended on condensers or on a cable on open circuit. Or it may be used to test other wattmeters, having the

potential current displaced 90° from the field current, either by the generating machine or by other means; or it may be used to show when a given current and a given electromotive force differ by 90° , or any other desired angle, and so employed to calibrate phase meters.

When a wattmeter or alternating ammeter is to be made very sensitive, that is to measure small power or small current, it is necessary to make the constant K large. If the instrument is compensated for the self-inductance of the moving coils one can put a larger number of turns on these coils than otherwise, and allow L_2 to have a relatively large value. This will give a greater sensibility without danger of error arising from self-inductance.¹

¹Since the above was written I have noticed that M. H. Abraham has used a capacity and a resistance to compensate in a similar manner an alternating moving coil galvanometer.