
Nov. 1886
LEWISTON
MAINE
3
SEE SHEET NO. 2
Main Canal
MAIN
MILL
LINCOLN
WATER
CROSS
NO. 5
NO. 7
R. C. PINGREE AND CO.
PLANING MILL & LUMBER YARD
R. C. PINGREE AND CO.
SAW MILL, SHINGLE, LATH AND SIDING MFD
(Closed in Winter)
LINCOLN BLOCK BOARDING HO.
GAY, WOODMAN AND CO. SHOE FAC.
HOME MFG CO. WOOLEN MILL
JONES BLOCK
M.C.R.R. TO BE FREIGHT DEPOT
Locomotive House
TURN TABLE
Androscoggin River
AVON
WEST BATES ST.
HYDRAULIC BRIDGE TO ROBBINS
Scattered piles Lumber
Lumber
Lumber Ware Hos
Scattered Lumber
Wood Pile
Fence
Driveway
Gate
Lumber
Wood Shed
Store No.
Store Hs.
Store Rm.
Dwg.
Tenement
Barber
Dunham & Shedd Stable & Livery
Tenant
Dye Ho.
Boiler Ho.
Engine Ho.
Steam Fitting
Grs.
Warren Thomas
Wood Ho.
Pipe Ho.
Tenements
Lumber Ware Ho. (Improved)
Daniels Planing Machine
Sawing & Planing Mch.
Sawing & Moulding Mch.
Sawing & Moulding Machine
Shingle Mch.
Shingle Machine
Lumber Shed
Fruit Preserve
Shafting
Engine 200 H.P.
Boiler 60 H.P.
Shingle Store Ho.
Lath Store Ho.
Shingle & Siding Mch's 1st
Log Sawing 2d
Shafting Bent
Slip
Platform 4'
Y.M. & S.C. Bridge
Night Watchman, 1 Asst. Same Men Watches G.T. Trunk Yard, Heat 7 Stoves (in Winter Only) Water Power, Electric Lights, Fuel 3 Mnths 130' 11½" Hose 3 Attachments 12 Inch Pipes
Night Watchman & Sunday Watchman & Queer Clock, 190 Heat (except Dry No. 3 Room) Lights, Gas, Fuel 3 Months & Wood. 4 Pipe with 50 2½" Hose 2½ & 1½ in. 2d Private Hyd. & 250 2½" Hose, Steam Power, 50 1½" Hose Att. in Blk Bd
Night & Sunday Watchmen, Heat 7 Stoves with Soft Coal, Lights Gas & Electric, Fuel 3 Months, Water Power, 1 Hose 2½" with 50' 1½" Hose Att. in Each Floor. City Water.
Night Watchman & Sunday & Holiday Clock, Heat 7 Stoves with Soft Coal, Lights Gas & Keb. Oil, Fuel 3 Months, Water Power, 46 Hand Extinguishers, 10 Pails, 3 Hose with 50 1½" Hose Att. Each Floor. City Water.
Night Watchman, 1 Asst. Same Men Watches G.T. Trunk Yard, Heat 7 Stoves (in Winter Only) Water Power, Electric Lights, Fuel 3 Months, 130' 11½" Hose 3 Attachments 12 Inch Pipes.
Night Watchman & Sunday Watchman, Heat 7 Stoves with Soft Coal, Lights Gas & Keb. Oil, Fuel 3 Months, Water Power, 46 Hand Extinguishers, 10 Pails, 3 Hose with 50 1½" Hose Att. Each Floor. City Water.
Night Watchmen, Heat 7 Stoves with Soft Coal, Lights Gas & Keb. Oil, Fuel 3 Months, Water Power, 46 Hand Extinguishers, 10 Pails, 3 Hose with 50 1½" Hose Att. Each Floor. City Water.
NOTE.
Night Watchmen Goes in L.E. Brown & Co. & Drives 1 Pin, in J. Millers 1 Pin & in D. B. Stevens 1 Pin. The Keys are so Arranged That He has to Go Through Each Building. The Same Man Drives Pins in the Grand Trunk Yard, & in R.C. Pingree & Co's Mill Above. Berry Clock with 3 Keys in All
Scale of Feet.
50 40 30 20 10 0 50 100 150
Map Division
31 JUL 1935
Library of Congress