

S3 Table. Dry matter (%) in slurry delivered to Thorsø Biogas plant during 2014. For information about farms, please refer to Table S1. Data were obtained from the biogas plant manager, Anders Nedergaard.

Farm ID 1)	Animal category	Housing system	DM (%)		
			Avg	min	max
G1	Dairy cattle	Cubicles	6.5	6	6.9
G2	Dairy cattle	Cubicles	5.6	4.8	6.4
G3	Finishing pigs	Partly slatted	4.1	3.3	5
G4	Finishing pigs	Partly slatted	5.2	4.6	6.3
G5	Dairy cattle	Cubicles	6.5	5.3	8.6
G6	Dairy cattle	Cubicles	9.2	9.2	9.2
G7	Farrowing sows	Loose, indiv confinement	3.5	1	7

- 1) Geographical coordinates: G1 - 56°21'10" N, 9°48'10" E; G2 - 56°18'02" N, 9°43'42" E; G3 - 56°20'13" N, 9°53'13" E; G4 - 56°21'06" N, 9°45'26" E; G5 - 56°21'29" N, 9°52'12" E; G6 - 56°16'11" N, 9°45'24" E; G7 - 56°21'02" N, 9°49'06" E.