DE GRUYTER
OPEN

DOI 10.2478/pesd-2014-0006

PESD, VOL. 8, no. 1, 2014

CLIMATIC AND HYDROLOGICAL HAZARDS IN JUNE 26-27, 2010 IN THE UPPER BASIN OF TROTUȘ. CASE STUDY: BETWEEN THE PROPOSED PREPARATION AND THE EFFECTS AT AGĂȘ (COUNTY OF BACĂU)

Viorel Paraschiv¹, Ovidiu-Miron Machidon² Doina Capsa³, Judit Găină⁴

Key words: hazards, water, climatic, flood, Trotuș

Abstract. The water catchment area of the Trotuș river lies on about 4340 square kilometers of which 66% are in the mountain area of the Central Group of the Eastern Carpathians (Moldo-Transilvans). In recent years the manifestation of natural hazards aggressiveness multiplied. In 2005 (12-13 July) and 2010 (26-27 June) Trotuș Valley was affected by strong floods that have produced great material damage. Hydro-technical works carried out after the 2005 summer hazard were swept away by the 2010 hazard, when were affected about 3,000 households in the upper *course* of the Trotuș, most of the damage being recorded on the Agăș Creek Valley to the confluence with the Trotuș, the administrative territory of the commune Agăș, where about 2000 household suffered. The late melting snow on the Ciuc and Tarcău Mountains peaks mixed with summer rains determined total isolation of the Cotumba, Sulța, Goioasa and Coșnea hamlets. Provisory bridges realized on the main roads on the side valleys, where are many hamlets, renewed in 2009 summer, were quickly clogged and then swept away by the rough waters of the Trotuș and its tributaries. In the upper basin of the Trotuș. Over the past 20 years have been recorded up phenomena of paroxysm of the climatic and hydrologic hazards among which the creeks Grohotiș and Sulța flooded the villages Goioasa and Sulța. On the 12-13 July, 2005 the Creek Agăș flooded a part of the Agăș village, about 2 kilometers, in line, of households. Drăcoiu creek broke the wall of channeled flood reached exceptional values, the maximum flow at Vrânceni hydrometric station being of 2800 cubic meters/s (probability of overflow 0,5%) and the flood volume here was the biggest of all the existing measurements.

¹ Economic Highschool of Tourism, Iași-Romania

² „Alexandru Ioan Cuza” University Iași,

³ Regional Meteorological Centre of Moldova-Romania

⁴ Highschool Sports, Roman-Neamț, Romania

1. Research methodology

- Analysis of weather characteristics overview for the area;

Correlation between temporal evolution of the use of the land and the construction of logging roads and of the mountain access, based on analysis of forestry cartographic materials (research projects, maps);

- Bibliographical study of the diagnosis drawn up by the institutions concerned about the structural analysis of the emergency situation;
- Identification of potential causes which can determine in the future similar hazards;
- Elementary impact study and the watershed more planning in the Trotus side.

2. Analysis of meteorological phenomena produced in the Trotus river basin (upstream from Comanești), 25-26 June 2010

At ground level in 25-26 June, 2010 UTC, the synoptic situation is the one on the synoptic map presented in pictures 1, 2. Romania was under a low pressure area which lies like a belt, from the South to the north-Eastern side of the continent with the main centers of low pressure disposed, one in the Northern side of the Black Sea, the other in the Scandinavian Peninsula.

Fig. 1. The frontal ground analysis in June 25, 2010 UTC, h12.00 (source: www.wetter3.de).

Fig. 2. The frontal ground analysis in June 26, 2010 UTC h6.00 (source: www.wetter3.de)

In the temperature land at the level 850 h Pa, our country is under the influence of an air mass of polar maritime origin, the whole territory of Moldavia being situated between 8-10° (fig 3,4).

CAPE provides a good measure of the degree of instability, representing the amount of potential energy for a high particle at the level of neutral buoyancy. This

item depends on the initial conditions of the particle and of the thermo-dynamic procedures used to raise the particle, the unit of measurement being J/kg (Jouli per kilogram).

Fig. 3. The surface-level air isobaric temperature of 850 hPa on June 25, 2010, h00.00 UTC

Fig. 4. The surface-level air isobaric temperature of 850 hPa on June 26, 2010, h6.00 UTC

(source: <http://www.wetter3.de/Archiv/>)

CAPE values for convective storms are about 1000 – 2000 J/kg. Sometimes the values could be more then 5000 J/kg.

Fig. 5 - Diagram Skew-T from June 25,2010 h 12 UTC
(sursa:<http://weather.uwyo.edu/upperair/europe.html>)

The diagram (fig.5) where is the vertical profile of the atmosphere and assesses the stability of the atmosphere in Bucharest on June 25, 2010 h 12.00 UTC, indicates: K-INDEX= 24 (chances to develop clouds Cb); CAPE= 295 J/kg; Total Index = 40 (probability to appear clouds Cb).

Abundant rainfall during the day of June 25, 2010 had front causes (picture 1) accompanied by the instability level during the afternoon (picture 5).

In the first part of the day of June 26, 2010 were met conditions by the occurrence of precipitation due to the hot thermal convection. All these happened as in the pictures from the satellite (fig. 6).

Fig. 6 a,b From satellite, in infrared, on June 25, 2010 h 12.00 UTC (a) and June 26, 2010 h 7.00 UTC (b) (source: <http://www.sat24.com/history.aspx>)

Tab. 1. The quantities of precipitation (l/m^2) confirmed by gauging stations situated in Trotus river basin (upstream from Comanesti)

Gauging stations	The quantities of precipitation	
	<i>Between June 25, 2010 h 3.00 and June 26, 2010 h 3.00</i>	<i>Between June 26, 2010 h 3.00 and June 27, 2010 h 3.00</i>
Lunca de Sus	24,5	41,1
Ghimeș-Făget	16,9	39,5
Goioasa	29,6	44,1
Ciobănuș	15,9	45,9

The rainy events from June 25-26, 2010 went to the accumulation of large quantities of atmospheric precipitations ($>55 \text{ l/m}^2$) in Trotus basin (upstream from Comanesti) – tab. 1. This way the level of Trotus river and its affluent have increased significantly being exceeded, local shares and flood attention (tab. 2).

Tab. 2. The registered shares confirmed by gauging stations situated in Trotus river basin (upstream from Comanesti)

Gauging stations	Attention share (m)	Flood share (m)	Danger share (m)	H (cm)		
				25 June 2010	26 June 2010	26 June 2010
Lunca de Sus	100	120	200	65	175	125
Ghimeș-Făget	150	250	300	110	174	168
Goioasa	150	200	300	88	238	175
Ciobănuș	130	200	250	100	136	109

2. Overall space requirements

In the middle and upper basin of Trotus river (upstream from Comanesti) there are 61% forestry, 34% agricultural lands (95% pastures and hayfields and 5% arable land), the other 5 % being used for other reasons (Dumitriu, 2006), meaning buildings, roads or unused lands. About the forestry it could be seen that near Trotus river it is less, comparing with other basins of the rivers. Here , in the Oriental Carpathians, the forestry lies on important areas (Văcărașu, 1984). After the river springs, going to the middle stream, the surface of the forestry increases. So, from the springs to the confluence with Ciughes the forestry is 30%. In the basins of Cold Valley, Tărhăuș and Ciughes the forestry is over 40 % and in those of Sulta and Camenca arrives to 60-70%. Over 80% are in the basins of Ciobanus and Asau streams. Beside this situation arrives another strange situation! Even if there were massive deforestations in the upper basin, at the beginning of the XX century, the damages were less regarding the soil from the middle basin. The maps and the documents prove this situation. The degradation of slopes is due to the fragmentation and of the slow slopes from the upper basin (Văcărașu, 1984). Another reason it could be the incorrect use of the pastures and hayfields comparing with the middle basin.

In the basins of Uz, Dofteana, Slănic, Oituz, Cașin the forestry increases from the springs to the lower basin. So, if in the upper and middle basin the forestry is over 70%, in the lower basin arrives to 30-40% (Uz, Oituz, Cașin). There is another situation in the upper basin of Uz(with the affluent Apa Lina and Rosu) and Oituz where the pastures and hayfields hold the main share. An increase of the process of erosion could be seen starting from the middle basin of Trotus river due to the pressure of humanity and fragmentation. These are determined by the lithological structure with effect in the dynamics of processes of beds from the major secondary valleys which empties into Trotus river.

3. Overall geographical conditions of Agas commune

The forestry is, statistically, about 60% from the surface of the commune (tab. 3) but the reality is different.

Tab. 3. Land structure

Agricultural land	Arable	240	0,1
	Pastures	4629	22,2
	Hayfields	3667	17,4
Non-agricultural land	Forests	12504	59,4
	Rivers	121	0,05
	Roads	254	0,1
	Built-up area	182	0,08
	Unused	50	0,02
Total		21040	100%

In Agas work about 400 persons the exploitation and processing of wood (2010, source: *The Mayor of the commune*): 200 on UFET Society and the others at private sawmills. The anthropic pressure on the forestry is overwhelmed and it seems that there is a big difference between the statistics and the reality. The forestry economy and agro-pastoral have 99% from the administrative surface of the commune. The arable lands are in built-up areas having soils of low fertility, especially podzols.

Analysis of geologic bibliography shows that in Panza of Audia (Brusturoasa-Agăș), because of the clay, which is the main, and the irrational use of the land, go to intense erosion in surface, especially on the right slope of the valley, between the confluence of Trotus with Popoi and Ciugheș. Other intense erosion areas were signed on left slope until the confluence with Cuchiniș. A proof of the irrational use of the lands could be seen on the left slope of Trotus valley, between the confluence with Cuchiniș and Camenca (Dumitriu, 2008), where appeared local badlands. The transit of silt in Agas is determined by the deep erosion, the torrentiality having the biggest contribution in forming silt (about 35%) thinking at the geological structure. Associated with the bank erosion and the massive landslides in the omonime valley, in the bed of the river appears accumulation of blocks. The roads for forestry exploitation have a contribution of 20-30% (Dumitriu, 2008) in forming badlands on important surfaces.

General conclusions

The main reasons which determined the floods in the last 10 years, with a maximum in 2005 and 2010, are:

- Important precipitations (over 130 l/mp) beside the water from the land, in spring, which comes from the snow
- The damage of the embankments because of to much water and the long period (over 20 days when appeared infiltrations – fig. 7. a, b)

Fig. 7. Effects of hazard event in Agăș

Fig. 8. Effects of hazard event in Agăș

- massive deforestation and unsuited agrotechnical works which help the erosion and lead to a bigger flow and important quantities of silt (fig. 7. a, b)
- The gullies and ditches are not enough, and the ones that exist in the rural area are not well used and kept (fig. 7. b)
- The clogging and the bad keeping of the gullies and ditches, which are not enough and properly for floods (fig. 8. a, b)
- Unauthorized buildings that appear in the flood areas

- Poverty, unauthorized buildings, bad projects, low quality materials and the lack of administrative rules for buildings (fig. 8. a, b)
- Overloaded transports on bridges and waste products which ruin the channels, already too few. Illegal deposits of sawdust from the major basins of Trotus and affluent are big pollutants
 - The works around the bridges are not made according the legal notices
 - The lack of enough materials and means of the local administration in case of floods

The ignorance of the people and the local administration how to interfere in case of climatic and hydrological hazards(to announce, to alarm the people).

Acknowledgments

Ovidiu-Miron Machidon is supported by a POSDRU grant no. 89/1.5/S/49944 “Developing the innovation capacity and improving the impact of research through post-doctoral programs”, Alexandru Ioan Cuza University, Iasi.

References

- Apostol L.** (2004) *Clima Subcarpaților Moldovei*. Editura Universității din Suceava
- Dumitriu D.** (2008) ”Modele de evaluare a bugetului de aluviuni în relație cu impactul antropoc dintr-un bazin hidrografic. Studiu de caz: bazinul râului Trotuș” – contract CNCSIS- UAIC Iași
- Dumitriu D., Niculiță M., Condorache D.** (2011) ”Downstream Variation in the Pebble Morphometry of the Trotuș River, Eastern Carpathians (Romania)” în *Forum geografic. Studii și cercetări de geografie și protecția mediului* - volume 10 (www.forumgeografic.ro)
- Grozavu A., Kocsis L.** (2006) ”Effets géomorphologiques de la crue de 12/13 juillet 2005 du Bassin versant du ruisseau Albele (Département de Bacău)” în *Analele științifice ale Universității ”Al.I.Cuza” Iași*. Tom LII, s.II-c, Geografie 2006: 60-66, Iași
- Văcărașu Iulia** (1984) ”Așezările de altitudine din zona montană a Trotușului și rolul lor în modificarea peisajului geografic înconjurător” în *Buletinul Societății de Științe Geografice din R.S.R.*, vol.VII: 88-93. București.
- * * * Date pluviometrice masurate in intervalul 25 – 27.06.2010 de statiile hidrometrice din cadrul Directiei de Ape Siret – S.G.A. Bacau;
- * * * www.sat24.com/history.aspx
- * * * <http://weather.uwyo.edu/upperair/europe.html>
- * * * www.wetter3.de/Archiv
- * * * www.wetter3.de